

# Oil Field Environmental Incident Summary

**Incident:** 20160305171513      **Date/Time of Notice:** 03/05/2016 17:15

**Responsible Party:** ONEOK Rockies Midstream

**Well Operator:** ONEOK ROCKIES MIDSTREAM

**Well Name:** Flat Top Compressor Station

**Field Name:**

**Well File #:**

**Date Incident:** 3/4/2016

**Time Incident:** 10:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 146

**Rng:** 101

**Sec:** 7

**Qtr:**

**Location Description:** 328 Fat Top road S Grassy Butte ND 58634

**Submitted By:** Byron Skaley

**Received By:**

**Contact Person:** Byron Skaley  
2700 Lincoln Ave. SE  
Sidney , MT 59270

**General Land Use:** Badlands Terrain

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 6 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Unknown

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Gallons	1	Gallons		

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Slight risk due to ember catching the grass on fire. Area burnt was 75yds X 100 yds.

**Areal Extent:**

**Potential Environmental Impacts:**

No potential environmental impact

**Action Taken or Planned:**

opened the valve that caused the liquid level pump not to activate.

**Wastes Disposal Location:**

**Agencies Involved:** US Forrest Service

**Updates**

---

**Date:** 3/7/2016    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, 1 gallon of oil was released onto topsoils at the location. Further follow-up needed.

---

**Date:** 3/16/2016    **Status:** Inspection

**Author:** Washek, Sandi

**Updated Oil Volume:** 1.00 gallons

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site at 1:05 p.m. The weather was partly cloudy, wind out of the NW at 20 mph, temp 41 degrees F. The area of impact is located outside the facility's fence area and to the southeast. The ground and vegetation have been burned. The soil shows no staining. The area burned is about 100 by 80 feet. No water was impacted. No additional follow-up is needed.